

Geoservex Hub India Pvt Limited

Address : F2/B1, Sai Krish,85, 4th Main Road,

CBI Colony, Perungudi.

Chennai· Tamil Nadu · 600 096 · India

GST No.: 33AAHCG5223B1Z7

Email: office-india@geoservex.com

Web: www.geoservex-india.com

**GEOSERVEX India Supervision Service Jobs Reference List**

S.No	Client Name	Description of Job
1	Ambuja Cements Ltd – Ropar	Cement Mill Discharge Head Replacement
2	ACC Limited – Kymore Cement Works	Kiln Support Adjustment and Cooler Alignment Check.
3	UltraTech Cement Ltd – Jharsguda Cement Works	Cement Mill Outlet Bearing Replacement
4	JK Lakshmi Cement, Sirohi	Kiln Support Roller Replacement
5	Ambuja Cement Ltd, Rabriyawas cement works	Kiln Shell Profile Study
6	Ambuja Cements Ltd, Darlaghat Cement works	Kiln shell replacement (Inlet shell with tire total 12 meters) including ground assembly of the shells.
7	Davao cement, Philippines	Kiln axis correction and thrust balancing of Kiln.
8	JK Lakshmi Cement, Sirohi	Slide shoe bearing replacement of ball mill
9	Saurashtra Cement Ltd, Ranavav	Root cause analysis of the vibration of the ball mill girth gear.
10	KJS Cement (I) Ltd, Satna	Kiln Shell Replacement
11	JK White cement, Gotan	Kiln Middle Tire Wear Ring Replacement
12	Keerthi Cement Industries	Kiln Support Roller Replacement and Coal Mill Girth Gear Reversal

Geoservex Hub India Pvt Limited

Address : F2/B1, Sai Krish,85, 4th Main Road,
CBI Colony, Perungudi.
Chennai· Tamil Nadu · 600 096 · India
GST No.: 33AAHCG5223B1Z7
Email: office-india@geoservex.com
Web: www.geoservex-india.com



13	Saurashtra Cement Limited	Trouble Shooting job in VRM
14	Ambuja Cement Limited	Supervision of Ball mill head replacement
15	TATA Chemical Limited	Cement Mill Vibration Issue Trouble Shooting
16	Andritz (China) Limited, China	Kiln Girth Gear & Pinion Replacement
17	Nuvoco Vistas Corporation Ltd, Jojobera	Cement Mill Vibration Issue Trouble Shooting
18	JK Laskmi Cement, Sirohi	Cowl Shell Replacement at Kiln #3
19	The India Cements Limited, Dalavoi	Supervision of Thrust Roller Replacement
20	Raysut Cement, Oman	Supervision of Kiln Shell Replacement
21	Dalmia Cement Ltd., Ariyalur	Supervision of Kiln Cowl Shell & Graphite Block Replacement
22	UltraTech Cement Ltd, Rawan	Supervision of Support Roller Replacement